

PISTON PUMP REPAIR KITS



FEATURES

- Genuine leather cup leathers
- Rubber gaskets
- High quality valve rubbers
- Stainless steel springs, cotter keys and washers
- Top quality packing



PART NO.	TO REPAIR PUMP	NO. OF CYLINDERS	CUP LEATHER SIZE	QUANTITY CTN	LIST PRICE-A
RK-K255	DURO MODEL K 255	1	1-3/8" x 5/8"	25	27.23
RK-K365	DURO MODEL K 365	1	1-5/8" x 5/8"	25	27.85
RK-E500	DURO MODEL E-500	2	1-3/8" x 5/8"	15	50.87
RK-E720	DURO MODEL E-720	2	1-5/8" x 5/8"	15	52.10
RK-GSW125	G.S.W. 300 1 1/4" SINGLE	1	1-1/4" x 5/8"	25	26.88
RK-GSW150	G.S.W. 300 1 1/2" SINGLE	1	1-1/2" x 5/8"	25	28.09

CIRCULATOR COUPLINGS



FEATURES

- Easy to install
- Quiet running
- Long life (no wearing surfaces)
- Superior alignment capabilities
- Easier on pump and motor
(Less rigidity puts less load on bearings and seals)

PART NO.	SHAFT SIZE	H.P. RATING	TORSION SPRING	END PIECES	A	B	C	LIST PRICE-A
24-15	1/2 x 1/2	1/12 - 1/3	#302 S.S.	Brass	1.20"	1.75"	1.00"	14.65
24-16	5/8 x 1/2	1/2 - 3/4	Spring Steel	Die Cast Alum Zinc Alloy	1.925"	2.250"	1.370"	56.70

*5/8 x 1/2 Shaft Bushing can be removed for use with 5/8" Shaft

NOTE: 24-15 Manufactured by SEALWELL PRODUCTS - 24-16 Manufactured by EASYLINK

CROSS REFERENCE CHART

BOSHART PART NO.	EASYLINK PART NO.	B&G OLD PART NO.	B&G NEW PART NO.	ARMSTRONG PART NO.
24-15	10010	PZ-4291 P2Z-12291	118705 118723	806026-001 806168-001
24-16	10023	PDZ-12291 P4Z-4291	118473 118709	810120-003 *807436-000 810120-006 *806137-000